

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2393	DATE	November 7 th 2016
MANUFACTURER	Rolls-Royce Motor Cars Ltd. (Japanese Importer: Rolls-Royce Motor Cars Ltd.)		
DESCRIPTION OF DEFECT	Due to improper installation of throttle module during assembly, the locating pin was not positioned correctly and it brakes. This could potentially result in the pedal stick during kick-down.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-681S	「Phantom SWB」	2016	2
ABA-681L	「Phantom EWB」	2016	2
		TOTAL	4