

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2404	DATE	2016/11/17
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain E-Class vehicles (213 platform), the seat frame of the rear seat bench could damage the wiring harness to the fuel system control unit and its electric wires. In case of a damaged wiring harness, the fuel pump, the fuel tank pressure sensor or the fuel gauge could fail, depending on the affected wire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-213042C	E200	2017	1,596
TOTAL			1,596