

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2406	DATE	November 28 th , 2016
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate handling of the material, a small number of output shafts of the drive shaft may be produced with defect material. Thus, when keep driving under high load condition, the drive shaft may break, and as a result, the propulsion can only transmitted to the front wheels and cannot transmit any longer to the rear wheels.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DLA-2Z15	BMW i8	2015	7
		TOTAL	7