

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

| | | | |
|-----------------------|--|------|---------------------------|
| CAMPAIGN No. | GAI-2411 | DATE | 28 th Nov 2016 |
| MANUFACTURE | Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.) | | |
| DESCRIPTION OF DEFECT | There is a possibility of a fuel leak via fuel pump sub harness because of a problem with the moulding tool used to manufacturer the sub harness. A fuel leak could heighten the risk of fire. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| EBL-GJ900 | STREET TWIN | 2016-2017 | 303 |
| | T100 | 2016-2017 | 2 |
| | STREET CUP | 2017 | 47 |
| EBL-HJ1200 | T120 | 2016-2017 | 264 |
| | THRUXTON | 2016 | 23 |
| | THRUXTON R | 2016 | 120 |
| | | TOTAL | 759 |