

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2412	DATE	Nov. 22 nd , 2016
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The airbag central sensor has been programmed with faulty software. In the event of a head-on or rear-end crash requiring activation of the passive safety systems, the seat belt tensioner, front airbags and active head restraint will not be activated, thus increasing the risk of injury to the occupants. The side airbag is not affected.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-SN30	BMW 535i Gran Turismo	2012	2
ABA-SN44	BMW 550i Gran Turismo	2012	1
ABA-SP44	BMW 550i xDrive Gran Turismo	2012	2
ABA-KA30	BMW 740i	2011 - 2012	56
ABA-KA44	BMW 750i	2011 – 2012	23
ABA-KB30	BMW 740Li	2011 – 2012	6
ABA-KB44	BMW 750Li	2011 – 2012	7
ABA-KB60	BMW 760Li	2012	3
		TOTAL	100