

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2413	DATE	Nov. 22 nd , 2016
MANUFACTURER	Rolls-Royce Motor Cars Ltd. (Japanese Importer: Rolls-Royce Motor Cars Ltd.)		
DESCRIPTION OF DEFECT	The airbag central sensor has been programmed with faulty software. In the event of a head-on or rear-end crash requiring activation of the passive safety systems, the seat belt tensioner, front airbags and active head restraint will not be activated, thus increasing the risk of injury to the occupants. The side airbag is not affected.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-664S	Rolls-Royce Ghost SWB	2011 - 2012	37
ABA-664L	Rolls-Royce Ghost EWB	2012	13
		TOTAL	50