

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3919	Date	November 2 , 2016
Manufacturer	Mitsubishi Nichiyu Forklift Co., Ltd..		
Description of Defect	The parking brake force of types of internal combustion engine powered forklift is not sufficient to satisfy the requirement with the amendment of the Announcement that prescribes details of safety regulations for road vehicles because the adjusting screw to determine the parking brake force was wrongly regulated.		

Model	Type	Commercial Name	Model Year Recalled	Number of Vehicles
Mitsubishi	EDM-F16D	Mitsubishi Forklift	2013/2014	4
	EDM-F18C		2013/2014/2015	24
	EDM-F37		2013/2014	3
	EDM-F14E		2013/2014/2015	49
	EBT-F34		2014/2015/2016	4
	EBT-F17D		2013/2014/2015	4
	EBT-F35		2016	1
	EBT-F13F		2013/2014/2015	4
	EDM-KF16D		2013/2014/2015	166
	EDM-KF18C		2013/2014/2015	342
	EBT-KF34		2013/2014/2015/2016	462
	EBT-KF17D		2013/2014/2015/2016	249
	Mitsubishi Nichiyu		YDM-F18D	
YDM-F14F			2015/2016	16
YDM-KF18D			2015/2016	103
Total				1435