

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3922	DATE	Nov . 25 , 2016
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-YA4	「EXIGA」	2008 ~ 2009	6,779
DBA-YA5		2008 ~ 2009	7,458
DBA-YA9		2009	180
CBA-YA5		2008 ~ 2009	6,251
		TOTAL	20,668