

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|---|------|-----------------|
| CAMPAIGN No. | 3924 | DATE | Nov . 25 , 2016 |
| MANUFACTURER | FUJI HEAVY INDUSTRIES LTD. | | |
| DESCRIPTION OF DEFECT | Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---------|-----------------|---------------------|-------------------|
| DBA-GH2 | 「IMPREZA」 | 2007 ~ 2009 | 29,625 |
| DBA-GH3 | | 2007 ~ 2009 | 11,415 |
| DBA-GH6 | | 2008 ~ 2009 | 897 |
| DBA-GH7 | | 2007 ~ 2009 | 6,941 |
| CBA-GH8 | | 2007 ~ 2009 | 5,892 |
| DBA-GE2 | | 2008 ~ 2009 | 1,964 |
| DBA-GE3 | | 2008 ~ 2009 | 1,254 |
| DBA-GE6 | | 2008 ~ 2009 | 775 |
| DBA-GE7 | | 2008 ~ 2009 | 989 |
| CBA-GRB | | 「WRX」 | 2007 ~ 2009 |
| CBA-GRF | 2007 ~ 2009 | | 2,179 |
| | | TOTAL | 69,368 |