

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3925	DATE	Nov . 25 , 2016
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BM9	「LEGACY」	2009	6,889
DBA-BR9		2009	16,837
DBA-BRF		2009	807
		TOTAL	24,533