

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 9 3 2	DATE	Nov.25.2016
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the front passenger airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could deteriorate after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture when the airbag is deployed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-Y50	FUGA	2009	725
DBA-PY50			677
DBA-PNY50			148
CBA-GY50			105
DBA-TU31	PRESARGE	2009	638
DBA-TNU31			194
CBA-PU31			71
CBA-SGE25	CARAVAN	2009~2012	2,957
CBF-VRE25			1,797

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ADF-VWE 25 LDF-VWE 25	CARAVAN	2009~2012	816
ADF-VWME 25 LDF-VWME 25			1,007
CBF-DSGE 25			1,578
ADF-DWGE 25 LDF-DWGE 25			38
ADF-DWMGE 25			393
CBF-CSGE 25			472
ADF-CWGE 25 LDF-CWGE 25			162
ADF-CWMGE 25 LDF-CWMGE 25			640
CBA-JSGE 25			ISUZU COMO
CBF-JVRE 25	22		
ADF-JVWE 25 LDF-JVWE 25	37		
ADF-JVWME 25 LDF-JVWME 25	44		
CBF-JDSGE 25	2		
CBF-JCSGE 25	3		
ADF-JCWGE 25 LDF-JCWGE 25	2		
ADF-JCWMGE 25 LDF-JCWMGE 25	5		
		TOTAL	