

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicle

CAMPAIGN No.	3934	DATE	November 25, 2016
MANUFACTURER	KOBELCO CONSTRUCTION MACHINERY CO.,LTD		
DESCRIPTION OF DEFECT	<p>With regard to a loading valve for regenerating of Diesel Particulate Filter (DPF) which was equipped on a wheel crane, the setting of valve operating pressure was improper. So when the valve was vibrated, it might cause crack on connector of hoses for hydraulic oil.</p> <p>Therefore, if the machine was continued to use without repair, the crack might be extended and hydraulic oil might be leaked. In the worst case, the machine would not be able to be operated.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CM03	MK650	2014-2016	4 units
CM03L	MK650	2014-2015	6 units
TOTAL			10