

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2368	DATE	DEC,21,2016
MANUFACTURE	KWANG YANG MOTOR CO.,LTD. 35, WAN HSING ST.SANMIN DIST. KAOHSIUNG, TAIWAN, R.O.C.. (Importer : Kymco Japan Inc. 6-1-1 Heiwajima, Otaku, Tokyo 144-0006, Japan)		
DESCRIPTION OF DEFECT	Due to the defect of configuration of throttle valve body, while riding, throttle valve return spring may come off and throttle valve becomes inoperable. In the worst case, throttle valve does close which may cause the engine speed to reduce not working properly.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SD10JA	SOONER50F	2013-2014	319 UNITS
		TOTAL	319 UNITS