

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-2415	DATE	December 13, 2016
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)		
DESCRIPTION OF DEFECT	With regards to the interior lamps equipped on the heavy-duty trucks, due to the inappropriate insulation treatment of the interior lamps' print circuit board (PCB), an internal short circuit may occur in cases where moister and/or dust adheres to the PCB's terminals. If the vehicle continues operation under these conditions, the short circuit may cause the PCB to heat up and in the worst case, the heat may damage or burnout the PCB.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QKG-H2TDA1	FH	2014-2016	164
QKG-H2TEA1		2014-2016	204
-H2TDA1-		2015	1
-H2TEA1-		2015-2016	8
Unspecified		2014-2016	311
		TOTAL	688