

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CANPAIGN No.	3948	DATE	Dec. 2. 2016
MANUFACTURER	SHINMAYWA INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Hydraulic pump bracket of garbage truck may crack while driving because of its strength shortage. When users continue using it, hydraulic pump may drop as the worst result.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TFG-NKR82ZAN	「ELF」	2012~2016	4
BKG-NKR85AN		2009~2010	6
SKG-NKR85AN		2011~2012	3
TKG-NKR85AN		2013~2013	4
TPG-NKR85AN		2015~2015	3
SKG-NKR85YN		2014~2015	5
TKG-NKR85YN		2015~2016	4
NFG-NMR82AN		2008~2009	2
SFG-NMR82AN		2011	1
SFG-NMR82ZN		2012	1
TFG-NMR82ZAN		2013~2015	14
TFG-NMR82ZN		2012~2015	11
BKG-NMR85AN		2008~2011	6
SKG-NMR85AN		2011~2011	7
SKG-NMR85N		2012~2012	6
TKG-NMR85AN		2012~2014	19
TKG-NMR85N		2012~2015	32
TPG-NMR85AN		2015	1
TPG-NMR85N		2015~2015	6
PDG-NPR75N		2011	1
SFG-NPR82ZN		2011	1
TFG-NPR82ZN		2013~2013	3
SKG-NPR85YN		2013~2015	11
TKG-NPR85YN		2015~2015	9

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
BDG-XZU304A	「DYNA」	2010	1	
SDG-XZU700		2013	1	
BKG-BKR85AN	「CONDOR」	2010~2011	2	
TKG-BPR85AN		2013	1	
SKG-LMR85N	「TITAN」	2011~2012	3	
PDG-FE73D	「CANTER」	2009~2011	6	
PDG-FE83DY		2008~2010	2	
SKG-FEA50		2011~2012	8	
TKG-FEA50		2012~2015	26	
TKG-FEA80		2014	1	
BJG-XKU304X	「DUTRO」	2010~2011	6	
BJG-XKU304Xkai		2009~2010	8	
SJG-XKU600X		2012	1	
TQG-XKU600M		2013~2014	2	
TQG-XKU600X		2013~2014	14	
TSG-XKU600X		2015~2016	15	
BDG-XZU304X		2009~2011	20	
BDG-XZU404Xkai		2009~2011	22	
BDG-XZU404M		2011	1	
TKG-XZU600X		2012~2016	42	
SKG-XZU685M		2012	1	
TKG-XZU700M		2012~2016	3	
		TOTAL	346	