

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3955	Date	December 8 , 2016
Manufacturer	Mitsubishi Nichiyu Forklift Co., Ltd..		
Description of Defect	The fuel pipe on the diesel engine may be broken because the pipe resonates at the engine speed of 1,800 rounds per minute and has excessive stress on a bend portion of the pipe enough to exceed fatigue strength of the pipe material. The pipe may crack in short time and may result in break in the worst case.		

Model	Type	Commercial Name	Model Year Recalled	Number of Vehicles
Mitsubishi	YDM-F18D	Mitsubishi Forklift	2015/2016	10
Nichiyu	YDM-F14F		2015/2016	23
	YDM-KF18D		2015/2016	210
Total				243