

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3964	DATE	December 15, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the automatic anti-glare room mirror, though the cause of the defect is not identified, the electronic circuit may be short-circuited, the plastic may be melt, a smoke may occur, and a control fuse may have been melted. If a melting fuse is occurred, the engine may not be able to start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-BM2AP	Mazda 「Axela」	2016	6
LDA-BM2AS		2016	26
LDA-BM2FP		2016	18
LDA-BM2FS		2016	39
DBA-BM5AP		2016	7
DBA-BM5AS		2016	20
DBA-BM5FP		2016	105
DBA-BM5FS		2016	166
LDA-BMLFS		2016	196
DAA-BYEFP		2016	11
LDA-GJ2AP		Mazda 「Atenza」	2016
LDA-GJ2AW	2016		43
LDA-GJ2FP	2016		31
LDA-GJ2FW	2016		64
DBA-GJ5FP	2016		11
DBA-GJ5FW	2016		21

DBA-GJEFP	Mazda 「Atenza」	2016	16
DBA-GJEFW		2016	21
DBA-CWFFW	Mazda 「Premacy」	2016	1
DBA-CWFFWN	Nissan 「Lafesta」	2016	8
		Total	831