

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	3968	DATE	DEC. 27,2016
MANUFACTURE	MITSUBISHI HEAVY INDUSTRIES,LTD.		
DESCRIPTION OF DEFECT	Due to the reason that the shape of brake pipe protector is inappropriate, the pipe protector contacts to the drag link at the maximum steering angle. In worst case, the vehicle does not conform to Safety standard clause 3 of Article 11.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FEB90	CANTER	2014-2016	22
		TOTAL	22