

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3971	DATE	December 22, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the auto dimming mirror, due to inappropriate parts manufacturing process, foreign substances may come into the electronic control board. Therefore the electronic control board may become short-circuited, the plastic housing may experience melting, and smoking may occur. In the worst case, the melting of the control fuse may occur, causing the engine to not restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-BM2AP	Mazda 「Axela」	2016	6
LDA-BM2AS		2016	26
LDA-BM2FP		2016	18
LDA-BM2FS		2016	39
DBA-BM5AP		2016	7
DBA-BM5AS		2016	20
DBA-BM5FP		2016	105
DBA-BM5FS		2016	166
LDA-BMLFS		2016	196
DAA-BYEFP		2016	11
LDA-GJ2AP	Mazda 「Atenza」	2016	21
LDA-GJ2AW		2016	43
LDA-GJ2FP		2016	31
LDA-GJ2FW		2016	64
DBA-GJ5FP		2016	11

DBA-GJ5FW		2016	21
DBA-GJEFP	Mazda 「Atenza」	2016	16
DBA-GJEFW		2016	21
DBA-CWFFW	Mazda 「Premacy」	2016	1
DBA-CWFFWN	Nissan 「Lafesta」	2016	8
		Total	831