

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2422	DATE	Jan. 11, 2017
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to management error in manufacturing process, side airbag, passenger airbag, front seat belt buckle, front seat back, rear seat belt, steering column, steering column combination switch and accelerator pedal may not be tightened properly. Therefore, these securing bolts may be loose with vibration while driving. If the vehicle is still used after this happens, these bolts will come off and operation of turn signal, wipers, steering wheel may be impossible and occupant protection may be reduced in a crash and airbags may not be deployed correctly when they are activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-BADDB	Bentayga	2017	41