

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3969	DATE	Jan.13.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger dual-stage airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GSE20	[IS250]	2012	1,136
DBA-GSE25			136
DBA-GSE20	[IS250C]		358
DBA-GSE21	[IS350]		133
	[IS350C]		113
DBA-USE20	[IS F]		156
CBA-LFA10	[LFA]	2010-2012	212
		TOTAL	2,244