VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3975	DATE	January 26 ,2017
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		The EVSC (electronic vehicle stability contol) of the heavy-duty truck model, does not work at all. The cause of this failure is the brake control unit improperly programmed. The truck model having this defect does not satisfy the Japan Safety Regulation.	

ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
QKG-CYY77B QPG-CYY77B	[GIGA]	2015-2016	121
		TOTAL	121