

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	3974	DATE	January. 27. 2017
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED		
DESCRIPTION OF DEFECT	In the container semi-trailer clamping device, welding of the bracket to connect the rod connecting the left and right twist locks is inappropriate, so there is something by which welded part fractures at the time of the vibration when running, or operation of a control lever. Therefore, there is a possibility that the container can not be fixed and released.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KFKGG340W	Container Semi Trailer	2016	48
		Total	48