

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2433	DATE	February 6 th , 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The defect involves the inflator of the affected front and/or side airbags (side, head, knee, front passenger airbag). Due to a fault in the supplier's production process, the possibly affected airbag may not deploy, although triggered properly in the event of an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-2A15	「BMW 218i Active Tourer」	2016	66
LDA-2C20	「BMW 218d Active Tourer」	2016	166
DBA-2A20	「BMW 218d xDrive Active Tourer」	2016	1
DLA-2C15	「BMW 225xe Active Tourer」	2016	2
DBA-2D15	「BMW 218i Gran Tourer」	2016	34
LDA-2E20	「BMW 218d Gran Tourer」	2016	54
DBA-2D20	「BMW 220i Gran Tourer」	2016	2
DBA-4P30	「BMW 440i」	2016	1
DBA-XG20	「BMW 523i」	2016	4
DBA-XG28	「BMW 528i」	2016	2
DBA-XL20	「BMW 523i Touring」	2016	1
ABA-FV44M	「BMW M5」	2016	1
DBA-XM12	「MINI One」	2016	10
DBA-XM15	「MINI Cooper」	2016	12
DBA-XM20	「MINI Cooper S」	2016	9
LDA-XN15	「MINI Cooper D」	2016	6
LDA-XN20	「MINI Cooper SD」	2016	17
DBA-XMJCW	「MINI JCW」	2016	38
DBA-XS12	「MINI One 5 Door」	2016	60
DBA-XS15	「MINI Cooper 5 Door」	2016	44
LDA-XT15	「MINI Cooper D 5 Door」	2016	25
LDA-XT20	「MINI Cooper SD 5 Door」	2016	16
DBA-LN15	「MINI One Clubman」	2016	2
	「MINI Cooper Clubman」	2016	10

DBA-LN20	「MINI Cooper S Clubman」	2016	22
	「MINI Cooper S Clubman A4」	2016	12
LDA-LR20	「MINI Cooper D Clubman」	2016	66
	「MINI Cooper SD Clubman」	2016	48
DBA-WG20	「MINI Cooper S Convertible」	2016	10
DBA-WHJCW	「MINI JCW Convertible」	2016	6
		Total	747