

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2434	DATE	February 6 th , 2017
MANUFACTURER	Rolls-Royce Motor Cars Ltd.		
DESCRIPTION OF DEFECT	The defect involves the inflator of the affected side airbags. Due to a fault in the supplier's production process, the possibly affected airbag may not deploy, although triggered properly in the event of an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-665C	「Rolls-Royce Dawn」	2016	3
		Total	3