

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-2440	DATE	15 th Feb 2017
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	Triumph T120 is supplied with heated handlebar grips. When engaged, the grips will heat up. Triumph includes a small air-gap between the end of the throttle twist grip rubber and the handlebar end weight to accommodate a small amount of expansion of the rubber grip once heated. The expansion air-gap on your motorcycle may be too small. A grip, when heated, could therefore expand beyond its air-gap and make contact with the handle bar end weight. In the event of contact, the throttle will no longer return as intended to its positive stop via spring force only, but will require some manual intervention to close the throttle. This presents an increased risk of a loss of control and vehicle crash. A cold (non-heated) grip has adequate clearance and will not bind as described above.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-HJ1200	T120	2016-2017	252
		TOTAL	252