

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2441	DATE	February 22, 2017
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>The leaks may occur in the solenoid valve which controls the gearbox heating circuit. As a result, fluid from the heating circuit may reach the connector for the engine control unit via the electrical wiring. If the engine control unit fails, the vehicle may break down.</p> <p>The coolant valve for gearbox (solenoid valve) must be replaced on the affected vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4HCDRF	A8 4.2 Quattro	2011-2012	595
ABA-4HCDRL	A8L 4.2 Quattro	2011-2012	134
		Total	729