

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3985	DATE	Feb. 2 2017
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty sightseeing buses, if the turn signals are operated for a long time repeatedly, the upper portion of the orange cap in the rear turn signal unit may melt. If the bus continues to be used in this condition, the portion will melt down to make a hole and the vapor from the cap will cloud the inside of the turn signal lens.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-MM96FH	「FUSO AERO ACE」	2015	1
		TOTAL	1