

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 9 8 8	DATE	Feb.2.2017
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the front passenger airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could deteriorate after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture when the airbag is deployed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
TA-AZ10	CUBE	2000~2001	17,232
TA-ANZ10			2,193
TA-NT30	X-TRAIL	2000~2001	4467
TA-T30			534
GH-PNT30			44
GF-A33	CEFIRO	2001	93
GF-PA33			30
TA-RM12	LIBERTY	2001	18
TA-RNM12			3
TA-FG10	BLUEBIRD SYLPY	2001	8
UA-QG10			3
TA-QNG10			3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
GE-DQGE 25	CARAVAN	2001	5
KG-DWGE 25			1
KG-DWMGE 25			2
GE-CQGE 25			2
KG-CWGE 25			1
KG-CWMGE 25			1
GE-VPE 25			6
		TOTAL	24,646