

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3995	DATE	Feb.14th.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>On the fuel system of the subject vehicles equipped with a diesel engine, due to insufficient strength of the fuel filter installed on the engine, a crack could develop in the fuel filter housing by changes of the fuel pressure and engine vibration. If the vehicle is continuously operated in this condition, the crack could expand causing the fuel filter case to become damaged and in the worst case, fuel could leak from the fuel filter.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
SDG-XZB40	[TOYOTA COASTER]	2014	225	
SDG-XZB50			531	
SDG-XBZ51			93	
SDG-XZB46V	[TOYOTA COASTER BIG VAN]		20	
SDG-XZB56V			9	
SDG-XZB40M	[HINO LIESSE]		104	
SDG-XZB50M			437	
SDG-XZB51M			67	
SDG-XZB56Y	[HINO LIESSE BIG VAN]		4	
		TOTAL	1,490	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
SDG-XZB50M	[HINO LIESSE]	2011	1	Engine was reinstalled as service parts
SDG-XZB51M		2012	1	
		TOTAL		2