

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3996	DATE	Feb.20 2017
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	For electric wire harness of street sweepers, found a part of wiring had been done improperly and it might interfere with a fixing bolt .Therefore, the wire could be damaged and could have a short circuit due to vibration while driving, then it would not be possible to start to run the engine for sweeper operation. It might have a fire at worst.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Note
PDG-NKR85Y	—	2009~2010	3	
SKG-NKR85N	—	2011	2	
TKG-NKR85N	—	2013	2	
TKG-AKR85N	—	2012	1	
		TOTAL	8	