

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3999	DATE	February.23. 2017
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	For some front seat belt pretensioners, ingredients of firelighter for activating the seat belt retractor were mixed in the wrong proportions. In the event of a collision, such firelighter cannot ignite properly, resulting in the pretensioner's non-actuation and eventual failure to retract the seat belt.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GB5	「FREED」 「FREED+」	2016	1,962
DBA-GB6			214
DAA-GB7			3,942
DAA-GB8			622
		TOTAL	6,740