

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2446	DATE	Feb. 21. 2017
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has determined that software errors in the Digital Motor Electronics-E (BMS-E) engine control unit can cause a faulty setting of the idle controller. In some cases, this faulty setting can result in the engine stopping running when it is at idle speed and declutched. Possible mechanical faults in the motorcycle can favor that the engine stops running. The occurrence of critical riding situations in consequence of this happening cannot be precluded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
G650GS	BMW G650GS	2013	15
G650GS-S	BMW G650GS-S	2013	10
		TOTAL	25