

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4008	DATE	Mar . 30 , 2017
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BM9	「LEGACY」	2010 ~ 2012	11,128
DBA-BMG		2012	1,324
DBA-BMM		2012	2,862
DBA-BR9		2010 ~ 2012	41,994
DBA-BRF		2010 ~ 2012	1,132
DBA-BRG		2012	4,241
DBA-BRM		2012	11,534
			TOTAL