

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4007	DATE	Mar . 30 , 2017
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GE2	「IMPREZA」	2010 ~ 2011	1,287
DBA-GE3		2010 ~ 2011	2,391
DBA-GE6		2010 ~ 2011	404
DBA-GE7		2010 ~ 2011	749
DBA-GH2		2010 ~ 2011	16,193
DBA-GH3		2010 ~ 2011	6,514
DBA-GH6		2010 ~ 2011	1,453
DBA-GH7		2010 ~ 2011	2,618
CBA-GH8		2010 ~ 2011	1,478
CBA-GRB		2010 ~ 2012	2,506
CBA-GRF		2010 ~ 2012	2,946
CBA-GVB		2010 ~ 2012	4,319
CBA-GVF		2010 ~ 2012	3,551
		TOTAL	46,409