

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4006	DATE	Mar . 30 , 2017
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-SH5	「FORESTER」	2010	145
DBA-SH5		2010 ~ 2012	13,557
CBA-SH9		2010 ~ 2012	988
DBA-SHJ		2010 ~ 2012	19,371
		TOTAL	34,061