

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4005	DATE	Mar . 30 , 2017
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the improper prevention of moisture absorption into propellant for passenger-side airbag inflator, propellant could degrade under the cycle of temperature and humidity. As a result of propellant degradation, inflator housing may rupture during airbag deployment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-YA4	「EXIGA」	2010 ~ 2012	7,857
CBA-YA5		2010	369
DBA-YA5		2010 ~ 2012	9,833
DBA-YA9		2010 ~ 2012	4,517
DBA-YAM		2012	4,548
		TOTAL	