

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2466	DATE	2017/3/30
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain ML vehicle (166 platform) the upper control arm might not be properly bolted onto the axle stub. Should the connection between upper control arm and axle stub not be assembled according to specifications, the tightening torque might not be sufficient and the wheel guidance could not be properly ensured, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-166024	GLE350d 4MATIC	2016	1
		TOTAL	1