

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic  Import Vehicles

CAMPAIGN No.	Gai-2459	DATE	Mar. 22. 2017
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has determined that in a few motorcycles, the screw connections on the relay lever of the spring strut were carried out incorrectly. This in turn may result in bad vehicle drivability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-S10CA	BMW S1000RR	2017	2
S1000RR	BMW S1000RR	2016	1
		TOTAL	3