

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2456	DATE	March 17, 2017
MANUFACTURER	FCA US LLC ( Japanese Importer : FCA Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	The Air Conditioning (A/C) hose may have been misrouted during the manufacturing process. The A/C hose may come in contact with the engine exhaust manifold heat shield. Prolonged A/C hose contact with the engine exhaust manifold heat shield, may result in a leak of the A/C refrigerant and/or A/C refrigerant oil. A/C refrigerant oil on a hot exhaust manifold could result in underhood smoke and/or an engine compartment fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-KL24P	「Cherokee」	2015	161
		Total	161