

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3967	DATE	March 3 ,2017
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	4axle container carrier (1) Rotating part protrudes outward more than the front fender because of the shape of 2nd, 3rd, and 4th axles are inadequate. Therefore, it does not fit into a Safety Regulations Article18. (2) The electric circuit of light (working lump) which is not going to be used during running installed at rear edge of the carrier is inadequate. Therefore, there is possibility to misidentify as a back lump.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTES
KL-CYJ51W4	GIGA	2003	2	(1)
PJ-CYJ51W5	GIGA	2004~2005	5	(1)
PJ-CYJ51W6	GIGA	2005~2006	5	(1)
PJ-CYJ77W6	GIGA	2007	2	(1)
PKG-CYJ77W8	GIGA	2008	1	(1)
PDG-CYJ77W8	GIGA	2010	1	(1)
LKG-CYJ77AA	GIGA	2012	1	(1)
QKG-CYJ77AA	GIGA	2012~2016	50	(1)50unit (2) 46unit
QPG-CYJ77BA	GIGA	2016	2	(1)
QKG-CYJ77BA	GIGA	2016~2017	66	(1)59unit (2)66unit
BDG-FW1EXYJ	HINO PROFIA	2008~2010	3	(1)
QKG-FW1EXBJ	HINO PROFIA	2013	1	(1)
QKG-FW1EXEJ	HINO PROFIA	2014	2	(1)
QPG-FW1EXEJ	HINO PROFIA	2016	4	(1)
TOTAL			145	sub-total (1)38unit (2)112unit