

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2453	DATE	03.03.2017
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	<p>SAFETY RECALL: Certain 2014 Model Year EcoSport. -Rear Twist Beam Pivot Bolt Replacement.</p> <p>Certain 2014 Model Year EcoSport vehicles built in Chennai (India) between 29th November, 2013 through 11th April, 2014.</p> <p>In some of the affected vehicles, there is a possibility that the Rear Twist Beam (RTB) bolt may not be tightened to specification, which may cause the RTB pivot bolt to break. If this occurs, vehicle handling and safe operation will be compromised increasing the risk of an accident. Dealers are required to replace the Rear Twist Beam bolt / nut and apply the new specified torque.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-MAJUEJ	EcoSport	2014	371 units
		TOTAL	371 units