

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2450	DATE	March 3 rd 2017
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	A replacement part relevant to former recalls have been possibly installed in service. The reason for this is that the Takata airbags are compatible with the originally installed airbags. It cannot be ruled out that, in case the replaced airbag is activated during a crash, the inflator ruptures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-AL19	BMW 318i	2000 – 2001	7,309
	BMW 318i Touring	2000 – 2001	2,245
	BMW 318Ci	2000 – 2001	1,135
GH-AY20	BMW 318i	2001	1,201
	BMW 318i Touring	2001	446
	BMW 318Ci	2001	398
GF-AM20	BMW 320i	2000	601
GH-AV22		2000 - 2001	8,705
GF-AM25	BMW 323i	2000	195
GH-AV25	BMW 325i	2000 - 2001	2,264
	BMW 325i Touring	2000 - 2001	858
GH-AV30	BMW 330i	2000 – 2001	2,067
	BMW 330Xi	2001	48
	BMW 330Ci	2000 – 2001	931
	BMW 330Ci Cabriolet	2000 – 2001	752
GH-DT25	BMW 525i	2000 – 2002	1,650
GH-DS25	BMW 525i Touring	2001	1
GH-DS25A		2001 – 2002	115
GH-DT30	BMW 530i	2000 – 2002	1,328
GH-DS30	BMW 530i Touring	2000 – 2002	107
GH-DN44	BMW 540i	2000 – 2002	277
GH-FA30	BMW X5	2000 - 2003	963
GH-FA30A		2002	1
GH-FB44		2000 - 2003	417

GH-FB44A		2002	1
GH-FB46	BMW X5 4.6is	2001 - 2002	56
GF-BL32	BMW M3	2000 - 2001	439
GH-DE50	BMW M5	2000 - 2001	39