

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4003	DATE	March 2, 2017
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to inappropriate control program for the cell motor unit measuring voltage and temperature in the traction battery, the traction force may not generate when the vehicle moves backward at the time the vehicle starts at upward slope with the condition that the battery voltage is temporarily changing. As a result, the vehicle may not start normally and descend the slope.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-HA3W	「i-MiEV」	2009~2010	3,373
		TOTAL	3,373