

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	GAI-2452	DATE	01/03/2017
MANUFACTURE	McLaren (Japanese Importer : McLaren Automotive ASIA Pte Ltd)		
DESCRIPTION OF DEFECT	Activation of a non-desiccated ammonium nitrate inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed on passenger side air bag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-MP4-12C	「McLaren MP4-12C」	2012	47
		TOTAL	47