

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	4025	DATE	24、4、2017
MANUFACTUR	NUTS CO.,LTD		
DESCRIPTION OF DEFECT	<p>In a fuel device of camping car, because the transference method of the fuel tank is inappropriate, the gap of a fuel pipe cover and the leaf spring becomes small then that cover and spring may come in contact at the time of a bad road run.</p> <p>Therefore when the customer continue using it in the same state, fuel pipe root part cracks and fuel might leak from the crack clause part in worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S201P	HIJET	2014-2015	6
EBD-S211P	HIJET	2014-2015	17
EBD-S500P	HIJET TRACK	2016	17
EBD-S510P	HIJET TRACK	2015-2016	18
		TOTAL	58