

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4039	DATE	April 21.2017
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	Rotary detection sensor, which detects traveling direction and speed of the agricultural tractor, improperly processes signals so that it could generate improper signal when the rotary detection gears are vibrated by engine start. It might cause control error resulting in stopping travel by fail safe mode.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「YT490」	2016	5
	「YT5101」	2016	1
	「YT5113」	2016	12
—	「YT5113C」	2016	1
TOTAL			19