

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4035	DATE	Apr.12.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>On an exhaust gas emission prevention system of the vehicle which has a diesel engine, because of an inappropriate material of a urea water injector fixation flange which is installed on the front pipe, the flange might crack due to corrosion and come off.</p> <p>If this occurs a urea water injector also comes off and exhaust gas does not meet the criteria.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-GDJ150W	[LAND CRUISER PRADO]	2015-2016	9,610
LDA-GDJ151W			2,345
		TOTAL	11,955