

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4026	DATE	2017/4/10
MANUFACTURER	YANMAR CONSTRUCTION EQUIPMENT CO. ,LTD.		
DESCRIPTION OF DEFECT	As for the hydraulic oil filter of shovel loader ,because the manufacturing was inadequate, the filters were assembled in reversed way.Therefore, in case of pressure increasing incide the filters in a condition the hydraulic oil is hard under the low tempureture , there is a risk which the filter might be broken for hydraulic oil to be leaked , or traveling might be impossible at the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
L2DA	「V2-3B」	2015 to 2017	32
WA117	「WA20-6」	2015 to 2017	26
TOTAL		2015 to 2017	58