

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4032	DATE	10 April 2017
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The heat insulator may be peeled off from the exhaust pipe. That may set accumulated straw debris on fire.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
XDN-C520	「WR575」	2013~2016	277
WDP-C614	「WR6100」	2013~2016	191
		TOTAL	468